

# AIR MED (ENGINEERING)

## Aircraft - G-PZIZ-Logbook Configuration Report

Tel: 01865 842887  
Page: 1 Of 2  
Date Printed: 05/04/2009

Engine													
<u>Manufacturer</u>		<u>Description</u>			<u>Part / Model Number</u>			<u>Serial Number</u>		<u>Location</u>			
Lycoming		Engine			TIO-540-J2BD			L-4341-61A		Left engine			
<u>TSN</u>	<u>CSN</u>	<u>LSN</u>	<u>OSN</u>	<u>TSO</u>	<u>CSO</u>	<u>LSO</u>	<u>OSO</u>	<u>Overhaul Date</u>					
67.00													
ATA	Description	Part Number	Serial Number	Location	<u>Times</u>			Hour	Cycle	<u>Limits</u>		Other	Date
					TSN (TSO)	CSN (CSO)	LSN (LSO)	OSN (OSO)			Landing		

	Fuel Pump	62E23187	IDN017FP	Left Engine	67.00				1800.00				
<b>29</b>	<b>HYDRAULIC POWER</b>												
29	Hydraulic Pump	1213HBG-310	OE4-0334	Left engine	( 67.00)	( )	( )	( )	1800.00				
<b>36</b>	<b>PNEUMATIC</b>												
36	Pneumatic Pump	441CC-7	130777	Left Engine	67.00				500.00				
<b>61</b>	<b>PROPELLERS</b>												
61-20	CSU	F-6-24	B9207T	Left Engine	( 67.00)	( )	( )	( )	1800.00				
<b>71</b>	<b>POWER PLANT</b>												
71	Differential Controller	LW-10098-85	KIO00694	Left engine	( 33.00)	( )	( )	( )	1800.00				
71	WASTEGATE	LW-12778	KJO00046	Left Engine	67.00				1800.00				
71	Density Controller	LW-16840-85	KIO00377	Left Engine	67.00				1800.00				
<b>73</b>	<b>ENGINE FUEL SYSTEMS</b>												
73	Injector	2524500-9	70CD2803	Left Engine	67.00				1800.00				
<b>74</b>	<b>IGNITION</b>												
74	Magneto	10-682910-13	G07JA066	Left engine	67.00				1800.00				
74-10	Alternator	ALU-8521LS	H114667	Left Engine	67.00				1800.00				
<b>80</b>	<b>STARTING</b>												
80	Starter	LW-15577	H091177	Left Engine	67.00				1800.00				

©ATP Maintenance Director

<b>81</b>	<b>TURBINES</b>						
81-20	TURBOCHARGER	LW-12463	LBL00274	Left Engine	67.00		1800.00