

# AIR MED (ENGINEERING)

## Aircraft - G-PZIZ-Logbook Configuration Report

Tel: 01865 842887

Page: 1 Of 2

Date Printed: 05/04/2009

Engine													
<u>Manufacturer</u>		<u>Description</u>			<u>Part / Model Number</u>			<u>Serial Number</u>		<u>Location</u>			
Lycoming		Engine			LTIO-540-J2BD			RL-2672-68A		RIGHT			
<u>TSN</u>	<u>CSN</u>	<u>LSN</u>	<u>OSN</u>	<u>TSO</u>	<u>CSO</u>	<u>LSO</u>	<u>OSO</u>	<u>Overhaul Date</u>					
UNK	UNK	UNK	UNK	33.00				24/11/2008					
											<u>Limits</u>		
<u>ATA</u>	<u>Description</u>	<u>Part Number</u>	<u>Serial Number</u>	<u>Location</u>	<u>TSN (TSO)</u>	<u>CSN (CSO)</u>	<u>LSN (LSO)</u>	<u>OSN (OSO)</u>	<u>Hour</u>	<u>Cycle</u>	<u>Landing</u>	<u>Other</u>	<u>Date</u>

<b>29</b>	<b>HYDRAULIC POWER</b>												
29	Hydraulic Pump	26802-008	OD8-0895		( 33.00)	( )	( )	( )	1800.00				
<b>36</b>	<b>PNEUMATIC</b>												
36	Pneumatic Pump	442CW-6	132492		33.00				500.00				
<b>61</b>	<b>PROPELLERS</b>												
61-20	CSU	F-6-24L	B2716T	RIGHT ENGIN	( 33.00)	( )	( )	( )	1800.00				
<b>71</b>	<b>POWER PLANT</b>												
71	Differential Controller	LW-10098-85	FE000114	Right Engine	( 33.00)	( )	( )	( )	1800.00				
71	Wastegate	LW-12778-85	FI000118	Right Engine	( 33.00)	( )	( )	( )	1800.00				
71	Density Controller	LW-16840-85	FG000399		( 33.00)	( )	( )	( )	1800.00				
<b>73</b>	<b>ENGINE FUEL SYSTEMS</b>												
73	Injector	2524500-9	70138601	Right Engine	( 33.00)	( )	( )	( )	1800.00				
73-00	FUEL PUMP MECHA	200F-5002	LHN037FP		( 33.00)	( )	( )	( )	1800.00				
<b>74</b>	<b>IGNITION</b>												
74	Magneto	10-682910-18	G02JA099	Right Engine	( 33.00)	( )	( )	( )	1800.00				
74-10	Alternator	ALU-8521LS	I082010		( 33.00)	( )	( )	( )	1800.00				
<b>80</b>	<b>STARTING</b>												
80	Starter Motor	MHB4014R	H110921		( 33.00)	( )	( )	( )	1800.00				

81

**TURBINES**

81-20 Turbocharger 409170-9001 AG026634 Right Engine ( 33.00) ( ) ( ) ( ) 1800.00